

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

429  
West  
1/2-1  
0.671 mi.  
3545 ft.

VAULT 6346  
WEST 24TH ST/NEPTUNE AVE  
BROOKLYN, NY

NY Spills S106000786  
N/A

Relative:  
Higher

Actual:  
1 ft.

SPILLS:

Name: VAULT 6346  
Address: WEST 24TH ST/NEPTUNE AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0110418 / 2003-05-01  
Facility ID: 0110418  
Facility Type: ER  
DER Facility ID: 75761  
Site ID: 82058  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2002-01-29  
Investigator: JHOCONNE  
Referred To: Not reported  
Reported to Dept: 2002-01-30  
CID: 396  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Affected Persons  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2002-01-30  
Spill Record Last Update: 2003-05-01  
Spiller Name: Not reported  
Spiller Company: UNKNOWN  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: PETE MCGUIRE  
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead\_DEC Field was O'CONNELL e2mis notes 141111 1/29/02 - 1402 J. CAMPANILE - 51238 - O.S. - EQUIP. GP., WHILE DOING INSPECTIONS, REPORTS FINDING APPROX 4 OZ OF AN UNKNOWN OIL ON APPROX 400 GALS OF WATER IN VS6346 (7B41). SPILL IS CONTAINED. NO SEWERS OR WATERWAYS AFFECTED. NO FIRE OR SMOKE INVOLVED. NO INJURIES RELATED TO SPILL. NO PRIVATE PROPERTY AFFECTED. CANNOT VERIFY THE EXISTENCE OF ANY SUMPS OR SEWER CONNECTIONS. NO MOVEMENT IN THE WATER. NO SUBSTANTIAL CRACKS IN STRUCTURE. NO PARKING 0900 - 1030, MON & THURS. TAG # 30060 PLACED IN STRUCTURE. CHAIN OF CUSTODY FORM # AA17373 FILLED OUT AND MARKED. 'E' (WITHIN 8 HRS) PRIORITY. TRANSFORMER IS A NON PCB UNIT THAT WAS INSTALLED ON 11/20/96. CREW IS UNABLE TO PRESSURE TEST UNIT DUE TO 'D' FAULT (TAG #1124) IN STRUCTURE. CLEANUP PENDING LAB RESULT. TJ - 50495 UPDATE 1-30-02 0100 HRS CHEM LAB # 02-00819-001 < 1 PPM LAZ # 04425 UPDATE: 1/30/02 - 1210 DUE TO THE INABILITY TO TAKE FDR 7B41 AT THIS TIME TO CLEAR THE 'D' FAULT, THE INCIDENT TYPE FOR THIS INCIDENT IS NOW CHANGED FROM SPILL - DEMINIMUS (24 HOUR UNDERGROUND) TO SPILL - OIL (UNKNOWN TYPE). TJ - 50495 Update - 3/27/02 1040hrs - S. Fuller reports pressure tested unit and found okay."

Remarks: "4 oz on 400 gal of water. clean up will be done after a feeder is

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

shut down. samples taken. ref # 141111."

All Materials:

Site ID: 82058  
Operable Unit ID: 848901  
Operable Unit: 01  
Material ID: 528044  
Material Code: 0064A  
Material Name: unknown material  
Case No.: Not reported  
Material FA: Other  
Quantity: 4.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported